

VIN	Model	SPEC. No.	Paint color	Upholstery	Rims	Run from	Soot contamination	Paint condition	Body	Chassis	Interior	Engine compartment	Other - comments
KPT20B1YSPP401172	TIVOLI	ELOLOXW5ND0258	BAS (navy blue)	bright /dark	Al.	battery	light	stains	car chrome dor - corrosion	tie rod ends, wishbones, exhaust system - corrosion	refreshment		dirty rims (rust stains)
KPT40B1ESPP094158	REXTON	E00LOGL7SD0317	LAK (black)	bright	Al.	booster	strong	matte /stains	Tylne lampy, relingi zmatowione; nadtopienia, zmatowienia grila; car chrome dor - corrosion	korozja - w tym ukt. wydechowego	Wymiana	soot; aluminum components, cooler, condenser - corrosion	
KPT60A1YSPP085277	KORANDO	E00M0HL5NS0637	WAA (white)	bright /dark	Al.	battery	strong	matte /stains	Tylne lampy, relingi, plastiki (np. lusterek) zmatowione; car chrome dor - corrosion	tie rod ends, exhaust system, rims - corrosion	replacement/washing	soot contamination; aluminum components, cooler, condenser - corrosion	
KPT40B1ESPP094102	REXTON	E00LOGL7SD0316	LAK (black)	bright	Al.	booster	light	ok	blotnik - rysa	wgniecenie zb. paliwa; lekka korozja ukt. wydechowego; korozja odlewów Al..	replacement/washing		
KPT60A1YSPP085276	KORANDO	E00M0HL5NS0635	RAF (red)	bright /dark	Al.	booster	strong	matte /stains	Tylne lampy, relingi, plastiki (np. lusterek) zmatowione; car chrome dor - corrosion	tie rod ends, exhaust system, rims - corrosion	replacement/washing	soot contamination; aluminum components, cooler, condenser - corrosion	komera cofania - zmatowienie
KPT60A1YSPP085382	KORANDO	E00M0HL5NS0426	ADA (grey)	bright	Al.	battery	strong	matte /stains	Tylne lampy, relingi, plastiki (np. lusterek) zmatowione; car chrome dor - corrosion	tie rod ends, exhaust system, rims - corrosion	replacement/washing	soot; aluminum components, cooler, condenser - corrosion	dirty rims (rust stains)
KPT60A1YSPP085364	KORANDO	E00M0HL5NS0641	RAF (red)	bright /dark	Al.	booster	strong	matte /stains	Tylne lampy, relingi, plastiki (np. lusterek) zmatowione; car chrome dor - corrosion	tie rod ends, exhaust system, rims - corrosion	replacement/washing	soot contamination; aluminum components, cooler, condenser - corrosion	wewnątrz zapach sadzy
KPT60A1YSPP085278	KORANDO	E00M0HL5NS0638	LAK (black)	bright /dark	Al.	battery	light	matte /stains	F maska - pkt. wybrzuszenia; F/L door- scratches	exhaust system (ostatni tłumnik) - corrosion	washing/refreshment		dirty rims (rust stains)
KPT60A1YSPP085367	KORANDO	E00M0HL5NS0416	ADA (grey)	grey	Al.	booster	strong	matte /stains	Tylne lampy, relingi zmatowione; nadtopienia, zmatowienia grila; maska - wgniecenie/NOK;	tie rod ends - corrosion	replacement/washing	korozja części z Al.	dirty rims (rust stains)
KPT40B1ESPP094159	REXTON	E00LOGL7SD0318	WAK (white)	dark	Al.	booster	strong	matte /stains	Tylne lampy, relingi zmatowione; nadtopienia, zmatowienia grila; car chrome dor - corrosion	wgniecenie zb. paliwa;	Wymiana	soot; aluminum components, cooler, condenser - corrosion	dirty rims (rust stains)
KPT20B1YSPP401118	TIVOLI	ELOLOXW5ND0128	BAS (navy blue)	bright /dark	Al.	battery	light	stains	car chrome dor - corrosion	tie rod ends, wishbones, exhaust system, screws - corrosion	refreshment		dirty rims (rust stains)
KPT20B1YSPP401107	TIVOLI	ELOLOXW5ND0300	RAV (red)	bright	Al.	battery	strong	stains	car chrome dor - corrosion	tie rod ends, wishbones, exhaust system, screws - corrosion	refreshment		dirty rims (rust stains)

KPT60A1YSPP085368	KORANDO	E00M0HL5 NS0416	WAK (white)	dark	Al.	booster	strong	matte /stains	Tylne lampy, relingi, plastiki (np. lusterek) zmatowione;	tie rod ends - corrosion	replacement/w ashing		
KPT20A1YSPP401124	TIVOLI	ELOLOXW5 NS0093	WAA (white)	bright /dark	steel	booster	light	stains		tie rod ends - corrosion	refreshment		dirty rims (rust stains)

VIN	Model	SPEC. No.	Paint color	Upholstery	Rims	Run from	Soot contamination	Paint condition	Body	Chasis	Interior	Engine compartment	Other - comments	Photo No.	Price net	Labor cost net PLN	Paint cost net PLN	Replacement parts net PLN	Additional cost net PLN	Total repair cost net PLN	Total repair cost net EUR	Operation costs Consignee PLN	Operation costs Consignee EUR	Total cost EUR	Cost EUR/ Price %
KPT40B1ESP094157	REXTON	E00LOGL7 SD0315	LAK (black)	bright	Al.	booster	strong	matte /stains	Tylny lampy, relingi zmatowione; nadtopienia, zmatowienia grilaj; car chrome dor - corrosion	wgniecenie zb. paliwa; korozja ukl. wydechowego	replacement/w ashing	soot; aluminum components, cooler, condenser - corrosion	Korozja klamek drzwi, przedziurawienie op. z pianką uszczelniającą oponę	01-01+01-28	31 445,00	5 340,00	4 259,90	28 199,28		37 799,18	8 702,45	389,00	90,08	8 792,53	28,0%
KPT40B1ESP094158	REXTON	E00LOGL7 SD0317	LAK (black)	bright	Al.	booster	strong	matte /stains	Tylny lampy, relingi zmatowione; nadtopienia, zmatowienia grilaj; car chrome dor - corrosion	korozja - w tym ukl. wydechowego	Wymiana	soot; aluminum components, cooler, condenser - corrosion		02-01+02-29	31 455,00	7 727,40	4 634,68	93 580,05		105 942,12	24 531,59	389,00	90,08	24 621,67	78,3%
KPT40B1ESP094159	REXTON	E00LOGL7 SD0318	WAK (white)	dark	Al.	booster	strong	matte /stains	Tylny lampy, relingi zmatowione; nadtopienia, zmatowienia grilaj; car chrome dor - corrosion	wgniecenie zb. paliwa;	Wymiana	soot; aluminum components, cooler, condenser - corrosion	dirty rims (rust stains)	03-01+03-29	31 545,00	10 668,00	14 893,05	138 429,95	454,00	164 445,00	37 859,95	389,00	90,08	37 950,03	120,3%
KPT40B1ESP093843	REXTON	E00LOGL5 SD0186	ACY (grey)	dark	Al.	booster	light	ok	tylna klapa - pkt. wgniotka	wgniecenie zb. paliwa;	Lekkie odświeżenie			04-01+04-23	31 075,00	5 456,00	4 749,78	19 475,43	54,00	29 735,21	6 845,89	389,00	90,08	6 935,97	22,3%
KPT40B1ESP094102	REXTON	E00LOGL7 SD0316	LAK (black)	bright	Al.	booster	light	ok	blotnik - rysa	wgniecenie zb. paliwa; lekka korozja ukl. wydechowego; korozja odlewów Al..	replacement/w ashing			05-01+05-20	32 015,00	10 704,00	7 662,22	106 317,08		124 683,30	28 861,29	389,00	90,08	28 951,37	90,4%
KPT60A1YSP085367	KORANDO	E00MOHLS NS0416	ADA (grey)	grey	Al.	booster	strong	matte /stains	Tylny lampy, relingi zmatowione; nadtopienia, zmatowienia grilaj; maska - wgniecenie/NOK;	tie rod ends - corrosion	replacement/w ashing	korozja części z Al.	dirty rims (rust stains)	06-01+06-22	15 880,00	8 562,00	7 765,34	65 257,54	254,00	81 838,88	18 841,65	389,00	90,08	18 931,73	119,2%
KPT60A1YSP085368	KORANDO	E00MOHLS NS0416	WAK (white)	dark	Al.	booster	strong	matte /stains	Tylny lampy, relingi, plastiki (np. lusterek) zmatowione;	tie rod ends - corrosion	replacement/w ashing			07-01+07-22	15 880,00	11 134,00	10 123,00	92 990,17		114 247,17	26 302,96	389,00	90,08	26 393,04	166,2%
KPAX62EESP203865	MUSSO	EL0NOUH5 SD0196	ADB (black)	dark	Al.	booster	light	ok	B/R - blotnik otarcie; F/L - nakładka blotnika - otarcia		Lekkie odświeżenie			08-01+08-16	24 555,00	2 580,00	2 944,08	13 127,97		18 652,05	4 294,25	389,00	90,08	4 384,33	17,9%
KPAX62EESP203871	MUSSO	EL0NOUH5 SD0207	WAA (white)	dark	steel	booster	light	ok		wgniecenie zb. paliwa	Lekkie odświeżenie	wygrzyzione przez zwierze wyciszenie kłapy silnika		09-01+09-16	21 375,00	4 008,00	2 160,00	18 427,68		24 595,69	5 662,62	389,00	90,08	5 752,70	26,9%
KPT60A1YSP085364	KORANDO	E00MOHLS NS0641	RAF (red)	bright /dark	Al.	booster	strong	matte /stains	Tylny lampy, relingi, plastiki (np. lusterek) zmatowione; car chrome dor - corrosion	tie rod ends, exhaust system, rims - corrosion	replacement/w ashing		wewnątrz zapach sadzy	10-01+10-22	15 920,00	6 744,00	3 142,86	65 449,14		75 336,00	17 344,56	389,00	90,08	17 434,64	109,5%
KPT60A1YSP085276	KORANDO	E00MOHLS NS0635	RAF (red)	bright /dark	Al.	booster	strong	matte /stains	Tylny lampy, relingi, plastiki (np. lusterek) zmatowione; car chrome dor - corrosion	tie rod ends, exhaust system, rims - corrosion	replacement/w ashing	aluminum components, cooler, condenser - corrosion	komera cofania - zmatowienie	11-01+11-24	16 330,00	6 524,00	3 709,60	57 681,83		67 915,43	15 636,14	389,00	90,08	15 726,22	96,3%
KPT60A1YSP085277	KORANDO	E00MOHLS NS0637	WAA (white)	bright /dark	Al.	battery	strong	matte /stains	Tylny lampy, relingi, plastiki (np. lusterek) zmatowione; car chrome dor - corrosion	tie rod ends, exhaust system, rims - corrosion	replacement/w ashing	aluminum components, cooler, condenser - corrosion		12-01+12-20	17 530,00	6 190,00	6 059,90	49 229,81		61 479,71	14 154,43	389,00	90,08	14 244,51	81,3%
KPT60A1YSP085382	KORANDO	E00MOHLS NS0426	ADA (grey)	bright	Al.	battery	strong	matte /stains	Tylny lampy, relingi, plastiki (np. lusterek) zmatowione; car chrome dor - corrosion	tie rod ends, exhaust system, rims - corrosion	replacement/w ashing	soot; aluminum components, cooler, condenser - corrosion	dirty rims (rust stains)	13-01+13-24	18 430,00	9 840,00	8 154,43	59 342,74	108,00	77 445,17	17 926,69	375,00	86,83	18 013,52	97,7%
KPT60A1YSP085278	KORANDO	E00MOHLS NS0638	LAK (black)	bright /dark	Al.	battery	light	matte /stains	F maska - pkt. wybrzuszenia; F/L door- scratches	exhaust system (ostatni tłumnik) - corrosion	washing/ refreshment		dirty rims (rust stains)	14-01+14-18	18 560,00	11 820,00	10 613,31	92 817,39	54,00	115 304,70	21 484,99	375,00	86,83	21 571,82	116,2%
KPT20B1YSP400718	TIVOLI GRAND	ELOLOXBS ND0159	WAA (white)	bright /dark	Al.	booster	light	ok		tie rod ends, exhaust system, rims - light corrosion	refreshment		dirty rims (rust stains)	15-01+15-18	18 905,00	4 156,00	4 033,87	21 426,29		29 616,16	6 818,48	389,00	90,08	6 908,56	36,5%
KPT20A1YSP401124	TIVOLI	ELOLOXWS NS0093	WAA (white)	bright /dark	steel	booster	light	stains		tie rod ends - corrosion	refreshment		dirty rims (rust stains)	16-01+16-14	13 015,00	9 178,00	5 780,73	100 150,73		115 109,27	26 501,38	389,00	90,08	26 591,46	204,3%
KPT20B1YSP401119	TIVOLI	ELOLOXWSN D0104	WAA (white)	bright /dark	Al.	booster	light	ok		Alu. components, tie rod ends, wishbones, exhaust system, rims - corrosion	refreshment			17-01+17-14	15 445,00	4 352,00	2 700,00	17 809,35		24 861,35	5 723,80	389,00	90,08	5 813,88	37,6%
KPT20B1YSP400925	TIVOLI	ELOLOXWS ND0142	ADA (grey)	bright /dark	Al.	battery	light	ok	F/L nakładka - otarcie	tie rod ends, car crossovers - corrosion	refreshment			18-01+18-22	16 235,00	4 908,00	4 485,79	25 493,61		34 887,40	8 032,08	375,00	86,83	8 118,91	50,0%
KPT20B1YSP400926	TIVOLI	ELOLOXWS ND0128	WAA (white)	bright	Al.	battery	light	stains	car chrome dor - corrosion	tie rod ends - corrosion	washing/ refreshment		dirty rims (rust stains), brak kompresora w zestawie naprawczym opon	19-01+19-16	17 755,00	6 818,00	3 734,61	13 681,48	54,00	24 288,09	5 591,80	375,00	86,83	5 678,63	32,0%
KPT20B1YSP401172	TIVOLI	ELOLOXWS ND0258	BAS (navy blue)	bright /dark	Al.	battery	light	stains	car chrome dor - corrosion	tie rod ends, wishbones, exhaust system - corrosion	refreshment		dirty rims (rust stains)	20-01+20-17	16 735,00	5 506,00	3 110,49	36 546,98		45 163,47	10 397,94	389,00	90,08	10 488,02	62,7%
KPT20B1YSP401118	TIVOLI	ELOLOXWS ND0128	BAS (navy blue)	bright /dark	Al.	battery	light	stains	car chrome dor - corrosion	tie rod ends, wishbones, exhaust system, screws - corrosion	refreshment		dirty rims (rust stains)	21-01+21-20	17 755,00	6 834,00	7 690,04	88 266,69	54,00	102 844,73	23 677,79	375,00	86,83	23 764,62	133,8%
KPT20B1YSP401107	TIVOLI	ELOLOXWS ND0300	RAV (red)	bright	Al.	battery	strong	stains	car chrome dor - corrosion	tie rod ends, wishbones, exhaust system, screws - corrosion	refreshment		dirty rims (rust stains)	22-01+22-24	18 015,00	7 014,00	7 567,85	98 701,31	144,00	113 427,16	26 114,19	375,00	86,83	26 201,02	145,4%

1 589 617,24 8 474,00

VIN	Model	SPEC. No.	Paint color	Upholstery	Rims	Run from	Soot contamination	Paint condition	Body	Chasis	Interior	Engine compartment	Other - comments	Photo No.	Model
KPT40B1ESP094157	TIVOLI	E00LOGL7SD0315	LAK (black)	bright	Al.	booster	strong	matte /stains	Tylny lampy, relingi zmatowione; nadtopienia, zmatowienia grila; car chrome dor - corrosion	wgniecenie zb. paliwa; korozja ukl wydechowego	replacement/w/ ashing	soot; aluminum components, cooler, condenser - corrosion	Korozja klamek drzwi, przedziurawienie op. z pianką uszczelniającą oponę	01-01+01-28	
KPT40B1ESP094158	REXTON	E00LOGL7SD0317	LAK (black)	bright	Al.	booster	strong	matte /stains	Tylny lampy, relingi zmatowione; nadtopienia, zmatowienia grila; car chrome dor - corrosion	korozja - w tym ukl. wydechowego	Wymiana	soot; aluminum components, cooler, condenser - corrosion		02-01+02-29	
KPT40B1ESP094159	REXTON	E00LOGL7SD0318	WAK (white)	dark	Al.	booster	strong	matte /stains	Tylny lampy, relingi zmatowione; nadtopienia, zmatowienia grila; car chrome dor - corrosion	wgniecenie zb. paliwa;	Wymiana	soot; aluminum components, cooler, condenser - corrosion	dirty rims (rust stains)	03-01+03-29	
KPT40B1ESP093843	REXTON	E00LOGL5SD0186	ACY (grey)	dark	Al.	booster	light	ok	tylna klapa - pkt. wgniotka	wgniecenie zb. paliwa;	Lekkie odświeżenie			04-01+04-23	
KPT40B1ESP094102	REXTON	E00LOGL7SD0316	LAK (black)	bright	Al.	booster	light	ok	blotnik - rysa	wgniecenie zb. paliwa; lekka korozja ukl. wydechowego; korozja odlewów Al.	replacement/w/ ashing			05-01+05-20	
KPT60A1YSP085367	KORANDO	E00MOHLSNS0416	ADA (grey)	grey	Al.	booster	strong	matte /stains	Tylny lampy, relingi zmatowione; nadtopienia, zmatowienia grila; maska - wgniecenie/NOK;	tie rod ends - corrosion	replacement/w/ ashing	korozja części z Al.	dirty rims (rust stains)	06-01+06-22	
KPT60A1YSP085368	KORANDO	E00MOHLSNS0416	WAK (white)	dark	Al.	booster	strong	matte /stains	Tylny lampy, relingi, plastik (np. lusterek) zmatowione;	tie rod ends - corrosion	replacement/w/ ashing			07-01+07-22	basic
KPAX62EESP203865	MUSSO	E00NOJH5SD0196	ADB (black)	dark	Al.	booster	light	ok	B/R - blotnik otarcie; F/L - nakładka blotnika - otarcia		Lekkie odświeżenie			08-01+08-16	
KPAX62EESP203871	MUSSO	E00NOJH5SD0207	WAA (white)	dark	steel	booster	light	ok		wgniecenie zb. paliwa	wygrzyzione przez zwierze wyciżenie klapy silnika			09-01+09-16	
KPT60A1YSP085364	KORANDO	E00MOHLSNS0641	RAF (red)	bright /dark	Al.	booster	strong	matte /stains	Tylny lampy, relingi, plastik (np. lusterek) zmatowione; car chrome dor - corrosion	tie rod ends, exhaust system, rims - corrosion	replacement/w/ ashing	aluminum components, cooler, condenser - corrosion	wewnątrz zapach sadzy	10-01+10-22	
KPT60A1YSP085276	KORANDO	E00MOHLSNS0635	RAF (red)	bright /dark	Al.	booster	strong	matte /stains	Tylny lampy, relingi, plastik (np. lusterek) zmatowione; car chrome dor - corrosion	tie rod ends, exhaust system, rims - corrosion	replacement/w/ ashing	soot contamination; aluminum components, cooler, condenser - corrosion	komera cofania - zmatowienie	11-01+11-24	
KPT60A1YSP085277	KORANDO	E00MOHLSNS0637	WAA (white)	bright /dark	Al.	battery	strong	matte /stains	Tylny lampy, relingi, plastik (np. lusterek) zmatowione; car chrome dor - corrosion	tie rod ends, exhaust system, rims - corrosion	replacement/w/ ashing	soot contamination; aluminum components, cooler, condenser - corrosion		12-01+12-20	
KPT60A1YSP085382	KORANDO	E00MOHLSNS0426	ADA (grey)	bright	Al.	battery	strong	matte /stains	Tylny lampy, relingi, plastik (np. lusterek) zmatowione; car chrome dor - corrosion	tie rod ends, exhaust system, rims - corrosion	replacement/w/ ashing	soot; aluminum components, cooler, condenser - corrosion	dirty rims (rust stains)	13-01+13-24	
KPT60A1YSP085278	KORANDO	E00MOHLSNS0638	LAK (black)	bright /dark	Al.	battery	light	matte /stains	F maska - pkt. wybrzuszenia; F/L door - scratches	exhaust system (ostatni tłumik) - corrosion	washing/ refreshment		dirty rims (rust stains)	14-01+14-18	
KPT26B1YSP400718	TIVOLI GRAND	EL0LOXBSND0159	WAA (white)	bright /dark	Al.	booster	light	ok		tie rod ends, exhaust system, rims - light corrosion	refreshment		dirty rims (rust stains)	15-01+15-18	
KPT20B1YSP401124	TIVOLI	EL0LOXW5NS0093	WAA (white)	bright /dark	steel	booster	light	stains		tie rod ends - corrosion	refreshment		dirty rims (rust stains)	16-01+16-14	
KPT20B1YSP401119	TIVOLI	EL0LOXW5ND0104	WAA (white)	bright /dark	Al.	booster	light	ok		Alu. components, tie rod ends, wishbones, exhaust system, rims - corrosion	refreshment			17-01+17-14	
KPT20B1YSP400925	TIVOLI	EL0LOXW5ND0142	ADA (grey)	bright /dark	Al.	battery	light	ok	F/L nakładka - otarcie	tie rod ends, car crossovers - corrosion	refreshment			18-01+18-22	
KPT20B1YSP400926	TIVOLI	EL0LOXW5ND0128	WAA (white)	bright	Al.	battery	light	stains	car chrome dor - corrosion	tie rod ends - corrosion	washing/ refreshment		dirty rims (rust stains), brak kompresora w zestawie naprawczym opon	19-01+19-16	basic
KPT20B1YSP401172	TIVOLI	EL0LOXW5ND0258	BAS (navy blue)	bright /dark	Al.	battery	light	stains	car chrome dor - corrosion	tie rod ends, wishbones, exhaust system - corrosion	refreshment		dirty rims (rust stains)	20-01+20-17	
KPT20B1YSP401118	TIVOLI	EL0LOXW5ND0128	BAS (navy blue)	bright /dark	Al.	battery	light	stains	car chrome dor - corrosion	tie rod ends, wishbones, exhaust system, screws - corrosion	refreshment		dirty rims (rust stains)	21-01+21-20	
KPT20B1YSP401107	TIVOLI	EL0LOXW5ND0300	RAV (red)	bright	Al.	battery	light	stains	car chrome dor - corrosion	tie rod ends, wishbones, exhaust system, screws - corrosion	refreshment		dirty rims (rust stains)	22-01+22-24	

Price net	Labor cost net PLN	Paint cost net PLN	Replacement parts net PLN	Additional cost net PLN	Total repair cost net PLN	Total repair cost net EUR	Operation costs Consignee PLN	Remarks
31 445,00	5 340,00	4 259,90	28 199,28		37 799,18	8 702,45	389,00	
31 455,00	1 789,33	1 073,19	21 669,07		24 531,59	24 531,59	389,00	
31 545,00	10 668,00	14 893,05	138 429,95	454,00	164 445,00	37 859,95	389,00	
31 075,00	5 456,00	4 749,78	19 475,43	54,00	29 735,21	6 845,89	389,00	
32 015,00	10 704,00	7 662,22	106 317,08		124 683,30	28 861,29	389,00	
15 880,00	8 562,00	7 765,34	65 257,54	254,00	81 838,88	18 841,65	389,00	
15 880,00	11 134,00	10 123,00	92 990,17		114 247,17	26 302,96	389,00	
24 555,00	2 580,00	2 944,08	13 127,97		18 652,05	4 294,25	389,00	
21 375,00	4 008,00	2 160,00	18 427,68		24 595,69	5 662,62	389,00	
15 920,00	6 744,00	3 142,86	65 449,14		75 336,00	17 344,56	389,00	
16 330,00	6 524,00	3 709,60	57 681,83		67 915,43	15 636,14	389,00	
17 530,00	6 190,00	6 059,90	49 229,81		61 479,71	14 154,43	389,00	
18 430,00	9 840,00	8 154,43	59 342,74	108,00	77 445,17	17 926,69	375,00	
18 560,00	11 820,00	10 613,31	92 817,39	54,00	115 304,70	21 484,99	375,00	
18 905,00	4 156,00	4 033,87	21 426,29		29 616,16	6 818,48	389,00	
13 015,00	9 178,00	5 780,73	100 150,73		115 109,27	26 501,38	389,00	
15 445,00	4 352,00	2 700,00	17 809,35		24 861,35	5 723,80	389,00	
16 235,00	4 908,00	4 485,79	25 493,61		34 887,40	8 032,08	375,00	
17 755,00	6 818,00	3 734,61	13 681,48	54,00	24 288,09	5 591,80	375,00	washing+ laundry +ozonation +conservation = 2.750.00 PLN
16 735,00	5 506,00	3 110,49	36 546,98		45 163,47	10 397,94	389,00	
17 755,00	6 834,00	7 690,04	88 266,69	54,00	102 844,73	23 677,79	375,00	
18 015,00	7 014,00	7 567,85	98 701,31	144,00	113 427,16	26 114,19	375,00	
					1 508 206,71		8 474,00	